Central Washington University ScholarWorks@CWU

All Undergraduate Projects

Undergraduate Student Projects

Spring 2020

Forge Burner

Caleb DesJardins Central Washington University, caleb.desjardins@cwu.edu

Follow this and additional works at: https://digitalcommons.cwu.edu/undergradproj

Part of the Heat Transfer, Combustion Commons, and the Manufacturing Commons

Recommended Citation

DesJardins, Caleb, "Forge Burner" (2020). *All Undergraduate Projects*. 120. https://digitalcommons.cwu.edu/undergradproj/120

This Undergraduate Project is brought to you for free and open access by the Undergraduate Student Projects at ScholarWorks@CWU. It has been accepted for inclusion in All Undergraduate Projects by an authorized administrator of ScholarWorks@CWU. For more information, please contact scholarworks@cwu.edu.

Forge Burner

Caleb DesJardins

Abstract	4
Introduction	5
Description	5
Motivation	5
Function Statement	5
Requirements	5
Engineering Merit	5
Scope of Effort	5
Success Criteria	6
Design and Analysis	6
Approach (RADD)	6
Design Description	6
Benchmark	6
Performance Predictions	6
Scope of Testing And Evaluation	7
Analyses	7
Device: Parts, Shapes and Conformation	7
Device Assembly, Attachments	7
Tolerances	7
Methods and Construction	8
Methods	8
Construction	8
Testing Methods	9
Budget	9
Schedule	10
Project Management	11
Discussion	11
Design Evolution / Performance Creep	11
Project Risk Analysis	12
Successful	12
Next Phase	13
Conclusion	13

Acknowledgment	13
References	14
Appendix A	15
A1: Flow rate of propane at 5psi gage.	15
A2: Flow rate of propane at 10psi gage.	16
A3: Flow rate of propane at 15psi gage.	17
A4: Flow rate of propane at 20psi gage.	18
A5: Flow rate of propane at 25psi gage.	19
A6: Flow rate of propane at 30psi gage.	20
A7: Flow rate of propane at 35psi gage.	21
A8: Flow rate of propane at 40 psi gage.	22
A9: Intake area as a function of valve height	23
A10: Required intake area for 10psi	24
A11: Required intake area for 20psi	25
A12: Required intake area for 30psi	26
A13: Required intake area for 40psi	27
Appendix B	28
20-0001 Burner Body	29
20-0002 Intake Valve	30
20-0003 Injector Bracket	31
20-0004 Burner Intake	32
20-0005 Burner Injector	33
10-0001 Burner Assembly	34
10-0002 Burner Assembly Exploded View	35
Appendix C	36
Parts List:	36
Appendix D	37
Appendix E	38
Appendix G	40
G1	40
G2	40
G3 Raw Data	40
G5	41
Appendix H	42

Appendix J

Abstract

Can small scale blacksmithing operations achieve a level of efficiency in their forge comparable to that of a large scale industry? The causes for the lack of efficiency needed to be pinpointed, and then the geometry of the existing design for the burner could be changed to fix the underlying issues, while still maintaining functionality. The problems with the previous design is the geometry of the intake giving an unknown air/fuel ratio, and the attachment of to the forge allowing the intake air to be contaminated by exhaust gasses. A burner needed to be designed that would solve these problems while maintaining the ability to output an oxidising flame for when an oxidised workpiece is desired. The final approach for finding the optimal intake geometry was based on a ratio between the propane injector outlet area and the air inlet area. This ratio was calculated based off of the desired air/fuel ratio and the density ratio between air and propane. This approach was compared with flow rate analysis at various propane pressure settings. The result of this calculation is that for any set propane pressure, the height of the intake opening needs to be .232 inches high. The input pressure of the propane does not affect this result. The intake valve was still designed to be adjustable so it could still produce an oxidising flame as desired. The optimized burner can be attached to a forge by a flange that prevents exhaust gasses from entering the intake.

Introduction

Description

Propane forge burners are often made by professional and hobbyist blacksmiths to step into an alternative to coal forges. A common theme among them is that they are built out of black iron pipe fittings. Making the burner out of pipe fittings makes it easy, however it results in a lack of efficiency due to the lack of precision in adjusting air/fuel ratio. High efficiency can be obtained by allowing excess air, but this puts more oxygen into the forge, making the metal inside oxidize too much. Burners are also usually attached with set screws holding them in a hole, which makes it difficult to remove the burner and allows the exhaust gas to get into the intake and make them run poorly.

Motivation

The motivation behind this project is a need for easy operation of a forge and efficient use of fuel. Blacksmithing requires proper timing to avoid overheating the material and working the material before it gets cold, so a burner that is easy to operate mitigates distraction from the heat cycles.

Function Statement

The Forge Burner is meant to burn propane more efficiently and with less excess oxygen than black iron pipe alternative.

Requirements

- Burner must be detachable within seconds.
- Intake must be adjustable with specific settings optimized for different propane pressures from 10 to 40 psi.
- Brings the forge floor up to 1000°F 20% faster than existing black iron pipe design.
- Forge exhaust must not be able to flow directly into the intake.

Engineering Merit

The merit behind engineering the burner is obtaining a specific efficiency. Fluid mechanics calculations are required to find the flow rates of the air and propane in order to optimize air-fuel ratio. The flow rate of air will have to be calculated for different intake settings to correspond with different propane pressures.

Scope of Effort

The scope of the project is limited to the geometry of the burner, the intake adjustment and the attachment system to the forge. The forge itself is not designed as it is a control between the designed burner tests and benchmark burner tests.

Success Criteria

At a given propane pressure, the burner would have to bring a forge up to temperature faster than a black iron pipe burner and reach a higher ultimate temperature. For a successful test, the burner will reach temperature 20% faster than the benchmark burner, while consuming 20% less fuel per minute.

Design and Analysis

Approach (RADD)

The burner is required to be 20% more efficient than the benchmark burner. This is done by analyzing the flow rates of air and propane and varying geometry to match stoichiometric ratio. Analyses are shown in appendix A. The design parameters are a flange on the body to block exhaust gasses and an adjustable intake with graduations to show the required valve setting for optimized air/fuel mixture for the current propane setting. The burner body with the flange is shown in appendix B 20-0001. Adjustable intake assembly is shown in appendix B 20-0002 through 20-0005.

Design Description

The burner consists of three main parts/assemblies. The intake assembly is mounted at the top of the burner and has a propane injector suspended above a conical air intake where the flow of propane entrains the air for combustion. The air and propane enters the burner body, where turbulence causes them to mix along the length of the mixing tube. At the end of the mixing tube is a nozzle for the gas to expand into and combust. Basic design is based off of the benchmark burner, however it has the following additions to improve efficiency: To block the flow of exhaust gas, the burner body has a flange that covers the burner hole. To adjust the airflow, the intake has a disc that is threaded onto the propane injector, so it can be raised up, or lowered down by spinning it to adjust intake area. The side of the injector bracket is graduated to show the height needed for each propane pressure. Drawings of all parts are shown in appendix B.

Benchmark

The benchmark is a black iron pipe burner and set screw attachment. The benchmark burner is based on a common design used by professional and hobbyist blacksmiths. There is no intake adjustment on the benchmark and attaching it to a forge with set screws allows for exhaust gasses to reach the intake.

Performance Predictions

The improved efficiency of the burner will result in a more even burn of the propane and a less oxidising flame. Uneven burning of propane in the benchmark burner is apparent based on the sound of the burner, and the sound of the designed burner's flame will be an even roar. Optimal air/fuel ratios will be achieved at any propane pressure setting within 10 psi increments as shown in appendix A10-A13. The exhaust gasses from the burner will not be allowed to

recirculate back into the intake as the burner port does not allow the gas to flow directly up. Air/fuel mixture is unknown for the benchmark burner, so exact improvement is unknown.

Scope of Testing And Evaluation

Testing will be limited to the resulting performance of the burner to bring a forge up to working temperature and to limit oxidation of the workpiece.

Analyses

The objective of the analysis was to find the optimal intake area for stoichiometric combustion. Mass flow rates of propane through the ejector were calculated for various input pressures through Bernoulli approximation. These values were used to calculate required intake area for stoichiometric combustion based on the assumption that air and fuel velocities would be equal. From these analyses, it was concluded that the intake area would be the same for any input pressure. The final approach for finding the optimal intake geometry was based on a ratio between the propane ejector outlet area and the air inlet area. This approach was discovered in "A Simple Method for the Design of Gas Burner Injectors." by CJ Lawn. This ratio was calculated based off of the desired air/fuel ratio and the density ratio between air and propane. This approach was compared with flow rate analysis at various propane pressure settings. The result of this calculation is that for any set propane pressure, the height of the intake opening needs to be .232 inches high. All green sheets for this analysis is shown in Appendix A.

Device: Parts, Shapes and Conformation

The general shape of the internal geometry of the burner tapers to a small area in the intake to accelerate it into the mixing tube, and then tapers out in the nozzle for the gas to expand for combustion. The burner body has a flange with holes for press fitting pins to locate it on the Forge coupler.

Device Assembly, Attachments

All parts will be threaded and bolted together in the configuration shown in appendix B 10-0001. The opening of the injector will be where the propane line and regulator will be attached.

Tolerances

All tolerances are given in ANSI Y14.5 drawings shown in appendix B 20-00001 through 20-00005. Most parts are given standard tolerance so parts fit together without interference. Holes in the flange of the burner body are given tighter tolerance as they will be reamed for a pin to be press fit into.

Methods and Construction

Methods

The components are constructed using the CWU machine lab. The burner body will be bored and turned on a lathe, and then holes will be drilled and reamed on a mill.

- The Burner Body is made up of a threaded pipe with a flange. The pipe and the flange will be machined separately and welded together in order to save time turning the whole thing out of cylindrical stock. Burner body drawing is shown in appendix B 20-0001.
- Internal geometry of the nozzle was bored out on a lathe.
- The Intake was the most difficult to manufacture as it had the most complicated features, and the work holding was an issue as the outside was tapered. The cylindrical stock was first drilled out on the lathe to get a through-hole for boring the internal taper. An arbor then needed to be designed to mount the intake in a chuck or vise so the outside taper and the flats could be machined. This was made by turning a taper on a piece of round stock to match the internal taper of the intake. A hole was then drilled and tapped so the intake could be bolted to it. The arbor also makes it easier to tap the holes in the side to accept the socket head screws. The drawing or the Intake is shown in appendix B 20-0004.
- The inside of the injector was drilled out of threaded rod. Outer features were then turned on a lathe and the end was threaded to attach to the injector bracket and accept the propane line. Injector dimensions are shown in appendix B 20-0005. Later iterations may be machined with finer thread pitch for finer adjustability.
- The intake valve was knurled on the outside and drilled and tapped in the center to be threaded onto the injector. These operations were done on a longer piece of stock and then was parted off. Due to the long diameter being parted on the lathe, it had to be done in multiple "bites" to make a groove wider than the parting tool to reduce friction on the tool.
- The injector bracket was rough-cut on the bandsaw, and final dimensions were machined on the mill out of a flat plate with appropriate holes drilled and tapped shown in appendix B 20-0003. Graduations were stamped on the side of the brackets showing the corresponding intake setting for a certain propane pressure setting.
- The forge couple was not fully machined as it will be easier to buy a pipe coupler and drill two holes in it to accept locating pins on the burner body flange.

Construction

The burner body is threaded at both ends with a pipe threader for the intake and nozzle to be threaded at both ends. Original design used locating pins that were press-fit into the holes in the burner body flange. The pins were switched out for socket head screws so the burner is able to be screwed into the forge if so desired. The screws still allow for the original attachment plan as they can be used as locating pins. The injector bracket was then attached to the intake with fasteners. The injector and intake valves are then threaded together, and the propane lines

can then be attached to the injector. Propane fitting requires a 45 degree coupler attached to the injector, a brass pipe nipple to attach to a ball valve, and an adapter to connect the ball valve to the propane line. The propane line comes from a regulator at the propane tank. The drawing tree in appendix B shows all parts as they connect to each other. Full assembly is shown in appendix B 10-0001 and 10-0002.

Testing Methods

The desired outcomes of the burner are higher efficiency to heat up a forge more quickly without a lean burn causing the workpiece to oxidize too much. The burner is tested against the benchmark black iron pipe burner. The sound of the burner is also a component of the test, as a smoother sounding burn is an indication of a more efficient burn. The forge will start cold in the testing and both burners will be timed to reach 1000 °F. The tests will have to take place on different days to make sure the forge is fully cooled between tests. Weather will have to be taken into account as different temperatures of ambient air affects heating rate and density of intake air. Oxidation testing will be done by maintaining 15 psi of propane pressure and placing a piece of steel in for a given amount of time. Plain carbon steel will be used for the test as it has a higher affinity for oxidation. The responding variable for the oxidation test will be mostly visual as it will be difficult to measure. The air-fuel mixture of the benchmark burner is unknown, therefore it is unknown how the two burners compare. If the benchmark is running lean, then the new burner will improve the excel in the oxidation test but increases in the efficiency will be minimal. If the benchmark is running a rich mixture, the new burner will greatly improve efficiency.

One round of the testing for the benchmark burner was completed to verify if the testing setup was valid. For the first test, the thermocouple reached the maximum heat within minutes while the forge was not even at full temperature. This result is most likely the result of the thermocouple probing along the roof of the forge. This was originally done because most heat treating kilns probe the temperature from the roof. However, heat treating kilns are usually heated slowly with electric coils; as opposed to a propane forge which is heated as quickly as possible with a burner. To get a more accurate reading on the forge, the thermocouple was moved to the bottom of the forge to measure the ambient temperature rather than all the heat rising to the top. One round of testing was completed for the benchmark and the engineered burner with this setup and it got the same result as the previous probe location. The final time-to-heat test was completed with the thermocouple under the floor brick. This was successful because the criteria for a forge being "up to temperature" is based on the floor brick being saturated with heat.

Budget

All raw materials and fittings were bought from Mcmaster-Carr. Total expected cost came out to \$137.53. Itemized budget is shown in appendix D. Mainly round stock was required

for the majority of the parts to be machined out of. All parts that show in the parts list in appendix C that are not shown in the budget were already owned. Labor was valued at \$100 per hour with no outsourced labor. Tentative schedule as shown in appendix E predicts 150.4 hours of labor is required, making the total labor cost equal \$15,040. Although labor is valued at \$100 per hour, it will be completed by a willing engineer accepting \$0 per hour, putting the total project cost at \$137.53. Funding may be sourced from CWU, however if CWU does not accept the request, it will have to be funded by the engineer (regardless of his/her poor financial status).

After all the raw materials and pipe fittings were bought, the total cost came out to \$140.27. This is close to what was budgeted as no deviations in the parts list has been made so far. All parts were ordered from McMaster-Carr as predicted and they all were delivered in a timely manner. All raw steel material ordered from McMaster-Carr was delivered within the tolerance specifications promised by the website. However, there are future plans to manufacture more nozzles out of ceramic so they can be used long-term instead of oxidizing away like the steel one. Machinable ceramic will be ordered from Maryland Lava Company. Pricing is not shown on the website, and scrap material will be requested to avoid going too far over budget.

Most of the unexpected expenditures came from the testing setup. It was assumed that the testing wouldn't cost anything since the forge was already owned. However, the forge required repairs before the testing could be done, so more insulation bricks were purchased. This added \$62.87 to the final cost. A thermocouple also needed to be purchased to measure the forge temperature. The thermocouple cost \$46.06, bringing the total testing cost to \$108.93. After adding the cost of testing materials, the total material cost for the project was \$249.20, this was 181.2% the predicted material cast for the project.

Schedule

The main deliverables for the project were the proposal with an initial design for the burner, parts that need machining, full assembly of device assembled with purchased parts, and a full test of the device with a testing report. The proposal for the project with the design is to be completed before December 6th, and all changes to design must be completed before the following January 7th. A fully assembled device must be completed before March 13th with various milestones for machined part completion in between. Testing began on March 31st and a full report of the test was completed before June 5th. All individual tasks were scheduled in appendix E with predicted time constraints for each task. Actual time spent is shown for only completed tasks.

The manufacturing process deviated from the original plan because the order of parts being manufactured needed to be changed. The original plan was designed so the most difficult part (the Intake) was made first. That way the hardest part is done first, and a lot of other parts attach to it, so they can be fit up as they are manufactured. The manufacturing order ended up being dictated by when raw material can be obtained. The injector was made first because the stock could be bought at ACE, and the injector bracket was made next because it was made from scrap. The rest of the parts are made from raw material from McMaster-Carr. The intake, nozzle, and burner body flange were completed in respective order as they were all made from the same piece of cylindrical stock. The majority of the machining processes took longer than expected. The timeline of parts being completed did not fall behind schedule, the individual processes just took more hours. The final assembly was completed on March 9th.

The testing deviated from the plan as it required some preliminary tests to find the final method. After the thermocouple was acquired, it was originally placed near the top of the forge, and the heat rose to the top and caused the probe to overheat. A new prob needed to be purchased, delaying the testing by a week. The next week of testing was then occupied by testing where the optimal place to probe for heat would be. Once the thermocouple was set up in the right place, the benchmark test and engineered burner test were completed. These two tests had to be completed across two days as the forge needed to cool down between tests.

Project Management

The project is overseen by Professor Charles Pringle, Dr. Craig Johnson, and Dr. John Choi. The success of the project will be facilitated by the guidance and expertise of the overseeing professors and machine lab support techs. Physical resources required are accessible in the CWU machine lab. Solidworks and AutoCAD are available on all CAD lab computers for designing the burner. Funding can be supported by the engineer, and funding from CWU will be requested. The project will be designed, built, and tested by the principal engineer. The engineer's resume is shown in appendix J.

Discussion

Design Evolution / Performance Creep

The burner was originally going to be designed with an electric blower to give forced induction. This design was later overlooked as it would not give adjustability in the air flow. The burner body was originally two inches shorter, however in order for the nozzle to sit in the right position in the forge with the length of the forge coupler and the thickness of the forge insulation, the extra length was added. After measuring the distance from the mating surface to the entrance to the forge, the flange on the burner body had to be moved upward so the nozzle would sit at the right height. The first design of the injector bracket was 3 inches tall, however analyses showed that it could be shortened and still give desired adjustability. The original design had a one inch inner diameter in the burner body, and the intake and nozzle. However later approaches to solving the flow rate problem suggested that a ³/₄ inch would give better results. The smaller diameter would also prevent the fuel from combusting in the mixture tube. The Burner Body was originally meant to be a pipe with a flange welded on, however, ³/₄ inch

pipe actually has a bigger inner diameter than the nominal size for historical reasons. Therefore, it needed to be machined out of mild steel tubing. Some design modifications had to be made to make the manufacturing process easier. One of the secondary plans for the burner body was to turn it out of 2 inch cylindrical stock, however that would be way too much material to remove. For practicality, the manufacturing process was changed to turning and tapping a piece of tubing and welding the flange on. The press-fit locating pins were swapped out for socket head screws as they still work as locating pins, but also open up the ability for the burner to be screwed to the forge if needed. This also made manufacturing easier as tapping the holes took less time than reaming and pressing pins would. The original instrumentation for the testing involved a thermocouple at the top of the forge to measure the ambient temperature of the forge. However this was problematic because most of the hot air rose to the roof and overheated the thermocouple even though the forge was barely up to temperature. The thermocouple was then moved to the bottom of the forge near the floor. This gave a better reading for the ambient air temperature of the forge. This is still not the most accurate way to measure the temperature in the time-to-heat test because a propane forge is considered "at temperature" when the floor brick is saturated with heat, but the air temperature exceeds 2000°F long before the floor is up to temperature. The thermocouple was ultimately placed under the floor brick to indicate when it is saturated with heat.

Project Risk Analysis

Significant risk is involved in the machining of parts and operation of the device. The engineer must receive required safety training for operation of the equipment being used to machine the parts for the device. Proper safety precautions must be taken when operating the device during use and testing. Specific risks and required precautions are shown in the job hazard analysis in appendix J.

Successful

The final design of the burner is successful as it has the required geometry to achieve the requirements. However, most of the analyses may not be a success as different approaches were analyzed for solving the flow rates and are more accurate than the previous approach. Changes in flow rate analyses did not affect the overall design, however it will affect the graduations that will be stamped into the side of the injector bracket and it affected the inner diameter of the burner body. The final assembly after the manufacturing process was successful in incorporating all of the critical geometry. The testing indicated improvements to the benchmark in every aspect; which varied from the prediction as the forge burner was assumed to improve in only two of the three aspects. The forge burner was promising from the beginning based on the sound. The benchmark had a choppy burn at first and took a while to even out, whereas the engineered forge burner gave a smooth flame throughout the test. The time to heat test showed a 16.2% improvement which fell short of the projected 20%, but it was a significant improvement nonetheless. The propane consumption was a huge improvement as the engineered forge burner consumed 53.6% as much fuel per minute than the benchmark burner. The oxidation sample for the benchmark showed much more surface distortion than that of the engineered forge burner; samples are shown in Appendix G5.

Next Phase

Because of the complexity of the question being analyzed for the project, the analysis of the flow rates in the burner required various assumptions to make the variables solvable. In the future, different approaches will be made for solving for the flow rates with different sets of assumptions. The different analytical approaches will be compared and the approach with the least assumptions will be used. These different approaches will be compared to the final solution does not yield the desired results during the testing phase. The injector bracket may need to be remade because a mistake in drilling the hole for the injector resulted in it sitting at a slight angle.

Conclusion

The Forge Burner is at a completed design and manufacturing stages and is ready to begin the testing process of the prototype. The analyses show that the geometry is optimized to facilitate the perfect air/fuel mixture for a variety of propane pressure settings. The testing phase will show if changes need to be made to the prototype. Optimal air/fuel ratios will be achieved at any propane pressure setting within 10 psi increments between 10 and 40 psi. Unlike the benchmark burner, the intake air will not be contaminated with exhaust gas. With this predictability, the designed burner was able to use 53.6% less fuel per minute and heat a forge 16.2% faster.

Acknowledgment

Professor Charles Pringle, Dr. Craig Johnson, and Dr. John Choi are to be acknowledged for facilitating the project and giving guidance for the engineer in completing the design. Dr. John Choi is especially responsible for helping with analyses with his expertise in fluid mechanics. Dr. John Choi contributed the most guidance for the proposal from weekly milestone checks.

References

"Carr." *McMaster*, www.mcmaster.com/.

- Lawn, C J. "A Simple Method for the Design of Gas Burner Injectors." Proceedings of the Institution of Mechanical Engineers, Part C: Journal of Mechanical Engineering Science, vol. 217, no. 2, 2003, pp. 237–246., doi:10.1243/095440603762826558.
- Çengel, Yunus A., et al. *Fundamentals of Thermal-Fluid Sciences*. McGraw-Hill Education, 2017.

Appendix A

aleb DesJardins MEJ 499A 11/8/19 · P2= 14.7psi Propane = 1.00 46 16hr/ft3 Flow rate through oriface at P. = 5 psi sase assume Pressure is constant Bernoulli approximation is sufficient method Bernoult Solution A= - Ta (3/1)2 - 1.198×10-10 A2 $P_{1} = 5psigage = 19.7 psia = 2836.8 \frac{15}{6t^{2}}$ $P_{2} = 14.7 psia = -2116.8 \frac{15}{6t^{2}}$ $P_{2} = 14.7 psia = -2116.8 \frac{15}{6t^{2}}$ $P_{3} = 14.7 psia = -2116.8 \frac{15}{6t^{2}}$ $P_{3} = 14.7 psia = -2116.8 \frac{15}{6t^{2}}$ $\frac{2836.8}{1.046} = 2116.8 + \frac{W^2}{2(327)}$ $\frac{10046(327)}{1.0046(327)} + \frac{W^2}{2(327)}$ $\frac{10046(327)}{1.0046(327)} + \frac{W^2}{2(327)}$ $\frac{10046(327)}{1.0046(327)} + \frac{W^2}{1.0046(327)}$ $\frac{100}{1.0046(327)} + \frac{W^2}{1.0046(327)}$

A1: Flow rate of propane at 5psi gage.

Caleb Destarding MET 484A 10/19/19
Given
$$P_1 = 29.7psi$$
 $P_2 = 14.7psi$
 $P_3 = 3556314a^2 = 2116.81^3/a^3$
 $P_3 = 1.00461607/a^3$
 $P_5 = 1.998 \times 10^{-5} ft^2$
Find
Flow rate through orifice
Assume
 $P_7 = 55076$ is constant
Bernoulli
Solution =0
 $P_1 + \sqrt{2} + \frac{1}{2} = \frac{P_2}{P_3} + \frac{V_1^2}{T_5} + \frac{1}{2}$
 $\frac{3556.8}{(10040)(32.7)} = \frac{2116.9}{(10046)(72.7)} + \frac{V_1^4}{1(371)}$
 $5354Fg = W$ $V = VA$ $m = Va$
 $V = 6.419\times10^{+4}$ $\frac{m = Va}{5}$ $\frac{1}{5}$

A2: Flow rate of propane at 10psi gage.

Coles Destending ME 14994 14/19
R = 14.7pi Property = 10046 4/47
P. = 14.7pi Property = 10046 4/47
P. = 1/6 A
$$(\frac{2}{64}, 1)^{5}$$

A $_{0}$ = 1.198 × 10⁻⁵ ft²
Front rate through on face of P. = 15.05 gess
Cosme
Pressure is constant
Pressure is constant

A3: Flow rate of propane at 15psi gage.

Caleb Destadins MET 489.1 Diven P2 = 14.7psi Ppropene = 1.0046 15/13 Find Flow rate through oriface at P=20 psi gase Pressure is constant Bernalli approximation is sufficient method Bernoulli equation Solution P. -- 20 PS, Sase - 34. 7, Si = 4996.8 15/6+2 P. -- 14. 1, ps, -- 2116.8 16/6+2 499(C.B - 2116.8 + W2 (1.0040)(32.D) - (1.0040)(322) + 2(32.2) 5733-63=W リーWA milp 75.75号=W V=.907×1035 m-911×103

A4: Flow rate of propane at 20psi gage.

Gua Cabb Destardus MET 489A W/Ma Pasta Pasta Propense - 1.0046 10 mg 3 P. 013/6a" A. = = { (3/6a)² A. = = { (3/6a)² A. = = 1 (0.8 × 10⁻⁵ f + ²) Flow rate thromoriface at Pi= 25ps gage Pressure is pustant . Bernalli approximation is sufficient method Pernoulli Solution $P_1 = 25 psi gse = 39.7 psia = 5716.8 \frac{1}{4t^2}$ $P_1 = 14.7 psia = 21168 \frac{1}{4t}$ $\frac{P_{1}}{P_{2}} + \frac{V_{1}}{V_{2}} + \frac{P_{1}}{F_{1}} + \frac{P_{2}}{P_{2}} + \frac{V_{1}}{F_{2}} + \frac{V_{1}}{F$ 57163 = 21168 + W2 (104 (2)2) = (1004 (32) + - 1022 $716703 = W^2$ $V = 1019 \times 10^2$ m = 1.0189

A5: Flow rate of propane at 25psi gage.

Deslardins 6/2014 ME cleb P.=49.7psi P_=14.7psi =643681942 = 2116.816/F+2 riven Propune: Propune: Propune: Propune: Propune: Propune: Propune: $A_0 = \frac{11}{64} \begin{pmatrix} 3 \\ 64 \end{pmatrix}$ $A_0 = 1.004 (10 m/s)$ $A_0 = 1.004 (10 m/s)$ $A_0 = \frac{11}{64} \begin{pmatrix} 3 \\ 64 \end{pmatrix}$ $A_0 = 1.098 \times 10^5 \text{ Ft}^2$ Flow rate through orifice. Assume . pressure is constant . Bernoulli opproximation is sufficient Bernaulli Solution =0 P_ + W/ + = - P2 + W2 + F2 Pg + 25 + = P5 + 25 + F2 $\frac{(4369)}{(10046)(322)} = \frac{21163}{(10046)(322)} + \frac{W^{2}}{2(522)}$ $\frac{9(00.44 - W^{2})}{9(00.44 - W^{2})} \quad iz W A_{o} \quad mz \dot{W} p$ $\frac{\dot{V} = V A_{o}}{\dot{V} = 1.111 \times 10^{-5}} \quad mz \dot{V} p$ 1pm

A6: Flow rate of propane at 30psi gage.

Caleb Destarding MET 4294A 10/25/10A (FIVEN P2=14.7psi P. Find rate through orifice at P.= 35 psi gage assume Bernoulli approximation is sufficient method Berneulli equation Solution P.=35 pri gage = 49.7 psi = 7156.2 10/ Ft2 P2=14.7p31=2116.816/F+2 P+ + + + + P2 + W2 + 74 $\frac{7156.9}{(1.0046)(37.7)} = \frac{2116.7}{(1.0046)(37.7)} + \frac{1}{2(317)}$ $\frac{1063725}{1063225} = W^{2} \qquad \dot{V} = WA \qquad \dot{m} = \dot{V}P \qquad \dot{m} = 1.205 \ \dot{m} = 1.20$

A7: Flow rate of propane at 35psi gage.

(aleb Destardins MET 489A P_=-14,7psi Propine=1.9046 16m/++3 Giren NT 3/64"S Flow rate through oriface at P. = 40 psi saye Pressure is constant Bernalli opproximation is sufficient method Benoulli A===== (3/(4)2 = 1.198×10-5 ft2 P.=40 psi gase = 54,7 psia = 7876.8 "\$+2 P2=14.7 psice = 2116.8 16/41 Pt + W. = P2 + V + 75 P5 + V. = P5 + 25 + 75 18768 - 1168 W 1396.03 = W V=VA 106.75 Ft/s=W V=1.279×103 106.75 Ft/s=W

A8: Flow rate of propane at 40 psi gage.

Caleb DesSurdins MET489 1/1/22/19 Given Burner intelse geometry: Appendix B 20-0002 20-0003 Find Intake Area as a function of Intake Value height. Assume knurling on intake value is negligible Soln. E.75-A = Cylendrical area - Exposed bracket A=2.25TTh-2(-75h) A=(2.25m-1.5) L

A9: Intake area as a function of valve height

Given Improprine= 6.444×10⁻⁴¹⁶ Nproprine=53.54 fts R=15.67 Area ratio of intake cone=222 Pair = .0765 10/41² Area ratio of intake cone=222 Pair = .0765 10/41² Find required intake area when proprine is set to 10p sig Assundanethed Bernoulli approx. is sufficient Wpropune = Wair at mixture tube Sala mair = Pringropure = , Q10098 A = Mair Mpropund Area ratio) Par A=.01105ft=1.5992in2

A10: Required intake area for 10psi

Vispropenez, All XIO 5 Wpropenez 75.72 ft Rais 67 Mit? Area ato at istake incassion Required intake area when propone is at 20psig Hornoulli approx. is sufficient Wpropune = War at misture tube Salv. mar= Lingopure Mair = . 01427 5 A= Wisir A= Noopre (Area rob.) Pair A=01111ft2 = 1.599312

A11: Required intake area for 20psi

Given mpropane = 1.117×10-310 Wordpane = G774-1/5 R=15.67 Pair = 07C5 1/4+3 Area ratio of intake Care = M2 Find Required intake area when propose is at 30psig. Assume/ method Bernoulli opprax. is sufficient Npropune Whir at mixture tube Sala Mair - R impropune =.0175 br A - Main Area rela) pair A=. 0112 ft = 1.601 in2

A12: Required intake area for 30psi

 $\frac{Gireh}{inpropune = 1.225 \times 10^{-3} \frac{16m}{5}} \qquad \text{Mpropune = 10625} \frac{44}{5}$ $R = 15.67 \qquad \text{Air of is of inflate conce = 222}$ $P_{cir} = .0765$ Find Req. intake area when propone is at 40,05:5 Assume/Method Bernalli approx. is sufficient Npropone=Wair at mixture sube Solh Main = Limpropene =. 020199 16m/s A = Main Noropene (Aria ratio) Dair A=.01114 ft2=1.6036in2

A13: Required intake area for 40psi

Appendix B





20-0001 Burner Body



20-0002 Intake Valve



20-0003 Injector Bracket



20-0004 Burner Intake



20-0005 Burner Injector



10-0001 Burner Assembly



10-0002 Burner Assembly Exploded View

Appendix C

Parts List:

- Burner body (Machined from material from McMaster-Carr)
- Burner Intake (Machined from material from McMaster-Carr)
- Injector (Machined from material from McMaster-Carr)
- Injector Bracket (Machined from material from McMaster-Carr)
- Intake valve (Machined from material from McMaster-Carr)
- Pipe coupler (owned)
- Pins (owned)
- Brass pipe nipple (Part number 568K153 from McMaster-Carr)
- Brass ball valve (Part number 5754T31 from McMaster-Carr)
- Brass pipe adapter (owned)
- Propane line (owned)
- Propane regulator (owned)
- Propane tank (owned)

Appendix D

Budget:

Item	Source	Price	Quantity	Subtotal	Cost
Steel Cyl. Stock	McMaster-Carr	60.00	1	60.00	64.80
Steel Pipe	McMaster-Carr	4.17	1	4.17	4.50
Steel Plate Stock	McMaster-Carr	1.71	1	1.71	1.85
Steel Injector Stock	McMaster-Carr	26.75	1	26.75	28.89
Brass Pipe Nipple	McMaster-Carr	2.47	1	2.47	2.67
Valve	McMaster-Carr	16.04	1	16.04	17.32
Pipe Adapter	McMaster-Carr	16.20	1	16.20	17.50
				Total:	137.53

Appendix E

Schedule:

Princip	bal Investigator.: Caleb DesJan	dins																		
		Duration	٦																	
TASK:	Description	Est.	Actual	%Corr S	Oc	tobe	r I	Nov	vem	nbe	F	Dec	: .	Janu	агу	February	March	April	May	June
ID		(hrs)	(hrs)																	
71	Proposal×							_	_	-	-		-	_	-					
1.	Outline	2	2				-	~			-	\sim	-	-						
10	John	3	3					٩,	0	V		1	-							
10	iriuu Mathada					_	-		0 :	0		-	-	-						
1.1	Avaluate	7	7				-		0	0	v	0			-					
10	Discussion	<u> </u>	6						^ ;;	0	^	^	-							
10	Discussion Determined Declark	2	2				-			Ċ.	0			-						
	Parts and Budget	3	3	<u>p</u>		_				Å.	Å.		-	-	-		_			
lg 1	Drawings	10	10				- 1	×.	Χ.	X	č.		_	_						
lh Ih	Schedule	3	3					_	_		X	X	-	-						_
ા	Summary & Appx	4	4					_			X	X		_						
	subtotal:	37	37			_		+	_				-	_						
2	Analuses	-				-		-	-	-	-	-		-	0					
2a	Fluid Mech =>Geo	10	20					×	× ·	X	X	×	1		\sim					
26	Stress Anal=>Geo	10	20						0.0	~	~	0	-	-						
20	Power Apal=>Geo					-	-	-	-				-	-						
20	Kipematic -> Geo							+	-					-	-					
20		E						-	-	-			-	-	-					
20	TOPETATICE => CIEU	15	20				-	-	-	-	_		-	-	-					
	SUDIO(a).	CI CI	20					+					-							
3	Documentation							-					-			\diamond				
3a	Part 1 Burner Bodu	2	2		X	X		+								\sim				
36	Part 2 Courbler	1	1				-	-				_						X		
30	Subassembly Attatchment	05	0.5					+	-		-	-	12	-				- 2		
34	Part 3 Intaka value	1	0.5	5 C C		V		+	-					-						
20	Part 4 lotaka	2	2			0	V	-	-	-			-	-	-					
26	Part 5 Injector	2	1			-	0		V	-			-	-	-					
20	Part Christer Preskat	- 1							0			-	-							
39	Cubasasablu lateka		1	2			- 7	1	-	-	-		0	-						
- Sri	Dubassembry milake						-	+	-				0 -	-						
31	Fart / NOZZIE	2	4				-	-	-	-			^		1					
2					-			-	-	-			-	-	-					
JK DI		-									0	0								
3	ANSI Y 14.5 Compi	5	4				A.	Ň	<u>~</u>	Ä	Å.	Å.		-	-					
3m	Make Ubject Files	2005	17.5			X	X	Χ.	Χ.	X	X	X		-						
	subtotal:	20.5	17.5	2		_		-		_			-	-						
4	Proposal Mods					-		+	-	-	-			-		0				
4a	Project Schedule	5	5										>	XX		×				
4h	Project Part Inv.	6	6											X	X					
40	Crit Des Beview*	5	5			-		+	-	-					X					
+0	subtotal:	16	16					+												
	SUDIUIdi.	10	10				-	-	-	-		-	-	-	1					

7 BatL Construction 7a< Make Part Inside 5 7b< Make Part Inside 5 7c Make Part Inside 7d Make Part Inside 9d Assemble Sub Inside 9d Assemble Sub Inside 9d Assemble Sub Inside 9d Assemble Sub Inside 9d Make Part Inside	_													~												
7 Make Part Inside 2 3 X X X X 7 Make Part Inside 1 3 X X X X X X 7 Make Part Inside Bracket 1 3 X X X X X X 7 Make Part Inside Part Inside Valve 2 3 X X X X X X X X 7 Make Part Inside Valve 2 3 X X X X X X X X 7 Make Part Inside Valve 2 3 X X X X X X X X 7 Make Part Inside Valve 2 3 X X X X X X X X 7 Make Part Inside Valve 1 5 X X X X X X X X 7 Make Part Inside Valve 1 5 X X X X X X X X 9 Make Part Coupler 2 2 X X X X X X X X 9 Assemble Sub Inside 0.5 0.5 X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X X	7	Part Construction							-				_	\diamond		_			_	_	_	-	_	-		_
7.0 Make Part Inake 5.7 7.0 Make Part Inake 5.7 7.0 Make Part Inake 2.4 7.7 Make Part Inake 2.4 7.7 Make Part Inake 2.5 7.7 Buy Part Ball Valve 0.5 9.7 Buy Part Ball Valve 1.5 7.1 Update Website 2.5 9.0 Device Construct 9.0 9.0 Assemble Sub Inlake 0.5 9.0 Assemble Sub Inlake 0.5 9.0 Device Construct 0.5 9.0 Assemble Sub Inlake 0.5 9.0 Device Construct 0.5 9.0 Assemble Sub Inlake 0.5 9.0 Device Evaluation 0.5 9.0 Device Evaluation 0.5 9.0 Device Evaluation 0.5 100 Debign Test/Scope 1.5 100 Debign Test/Scope 1.5 101 Did Definang/Dess 3.5 101 Did Definang/Dess 3.5 101 Did Pareneters 1.1 101 Did Definang/Dess 3.5 101 Test/Scope 1.1 101 Did Definang/Dess 3.5 101 Test/Scope 1.1 101 Did Pef	/a	Make Part Injector	2	3					X	X						_			_		_	-	_	_		_
72 Make Part Indue Eracket 1 3 X X X 72 Make Part Indue Valve 2 3 X X X 76 Make Part Indue Valve 0.5 0.5 X X X X 76 Make Part Indue Valve 0.5 0.5 X </td <td>/b</td> <td>Make Part Intake</td> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>10</td> <td></td> <td>XX</td> <td>-</td> <td></td> <td>_</td> <td></td> <td></td> <td>_</td> <td>-</td> <td>-</td> <td>-</td> <td>_</td> <td>-</td> <td></td> <td>_</td>	/b	Make Part Intake	5								10		XX	-		_			_	-	-	-	_	-		_
7d Make Part Hatke Valve 2 4 A 7r E Make Part Indike Valve 0.5 0.5 X 7g Make Part Nozzle 4 3 7h Make Part Nozzle 4 3 7h Make Part Nozzle 4 3 7h Update Website 1 5 9 Device Construct X X 9 Se Casemble Sub Attachment 0.2 0.2 9 Device Evaluation X X 10 Device Evaluation X X 10b Design Test Scope 1 X 10b Design Test Scope 1 X 10b Performer Evaluation 5 X 10b Performer Evaluation 5 X 10b Harder Performer Evaluation <td>/c</td> <td>Make Part Intake Bracket</td> <td>1</td> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>X</td> <td>X</td> <td></td> <td></td> <td></td> <td></td> <td>_</td> <td></td> <td></td> <td>_</td> <td></td> <td></td> <td>-</td> <td>_</td> <td></td> <td></td> <td>_</td>	/c	Make Part Intake Bracket	1	3						X	X					_			_			-	_			_
7F Buy Part Indike Valve 2 3 X X 7F Buy Part Soupler 2 2 X X X 7M Make Part Soupler 2 2 X X X X 7M Make Part Soupler 2 2 X X X X X 9 Device Construct 3 X X X X X 9 Device Construct 3 X X X X X 9 Device Construct 0 0 X X X X 9 Device Construct 0 0 X X X X 9 Device Construct 0 0 X X X X 9 Device Construct 0 0 X X X X X 9 Device Construct 0 X X X X X 9 Device Construct 0 0 X X X X 10 Device Evaluation	/d	Make Part Burner Body	2	4	1				-					X		_			_		_	-	-	-		_
7/7 Bduy Part Ball Valve 0.5 0.5 .X 7/9 Make Part Nozzle 4 3 7/1 Update Website 2 2 7/1 Update Website 1 5 9 Device Construct X X 9 Device Construct X X 9 Device Construct X X 9 Device Lonatruct X X 9 Device Lonatruct X X 9 Device Devictures 1 X 9 Device Evaluation X X 9 Device Evaluation X X 10 Device Evaluation X X 10 Device Evaluation X X 10 Device Statest sheets 2 X 10 Device Statest sheets 2 X 10 Device Statest sheets 2 X 10 Take Testing Pics 1 X 10 Test Statest 5 X 10 Test Statesheets 2 X	7e	Make Part Intake Valve	2	3				_	1.1			Х			_				_				_	-		-
7g Make Fart Nozzle 4 3 7h Make Fart Coupler 2 2 7h Update Website 1 5 9 Device Construct × × 9a Assemble Sub Intake 0.5 × × 9b Assemble Sub Intake 0.5 × × 9c Assemble Sub Intake 0.5 × × 9d Assemble Sub Intake 0.5 × × 9d Assemble Sub Intake 0.5 × × 9d Assemble Sub Intake 0.5 × × 9f Update Website 0.2 2 × 9f Update Website 0.2 2 × 9f Update Website 0.2 2 × 10b Design Test8.Scope 1 5 × 10b Plan analyses 3 5 × × 10b Plan analyses 3 5 × × 10b Plan analyses 1 × × × 10b Plan analyses 1 × × × 10b Take Testing Pics 1 1 × <td< td=""><td>76</td><td>Buy Part Ball Valve</td><td>0.5</td><td>0.5</td><td></td><td></td><td></td><td></td><td>X</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	76	Buy Part Ball Valve	0.5	0.5					X																	
7h Make Part Coupler 2 2 X X X 7h Update Website 1 5 X X X X X 9 Device Construct 0 X	7g	Make Part Nozzle	4	3										X												
Till Update Website 1 5 X X X X X X 9 Device Construct -	7h	Make Part Coupler	2	2																	X					
subtotal: 19.5 30.5 9 Device Construct	- 7i	Update Website	1	5									X				X				X					
9 Device Construct 0 0 9e Assemble Sub Attatchment 0.2 0.2 9b Assemble Sub Intake 0.5 × 9c Assemble Sub Intake 0.5 × 9d Assemble Subtate 2.4 × 9d Assemble Subtate 2.4 × 9d Intervent State 1 × 9d InterventState 1 × 9d InterventState 1 × 10b Design Test&Scope 1.5 × 10c Dbtain resources 1 × 10d Make test sheets 2.1 × 10d Pater Ban* 1.2 × 10f Destroment Forge 3.3 × 10g Test Plan* 1.2 × 10h Pater Rep Cutine 3.3 × × 10h Take Rep Cutine 3.3 × ×		subtotal:	19.5	30.5									-			_						-		-		
9a Assemble Sub Attachment 0.2 0.2 9b Assemble Sub Intake 0.5 0.5 9c 9c 0.5 0.5 9c 11 11 0.5 9c 0.5 0.5 0.5 9c 11 0.5 0.5 9c 11 0.5 0.5 9c 0.2 0.5 0.5 9c 0.2 0.5 0.5 9c 0.2 0.5 0.5 9c 0.5 0.5 0.5 9c 11 0.5 0.5 10b Plant resources 1 0.5 10c Dtain resources 1 0.5 10b Hoard 0.5 4 10b Update Website 0.5 4 10b No No No	9	Device Construct											-		0				-		-		-	-		
3b Assemble Sub Intake 0.5 0.5 3c	9a	Assemble Sub Attatchment	0.2	0.2											*						X	2		-		-
Sc Non-Net Obstantion No. 9d Assemble Burner 0.5 0.5 9e Take Dev Pictures 1 1 9e Take Dev Pictures 0.2 2 10 Device Evaluation X 10a List Parameters 1 1 10b Lesign Test&Scope 1 X 10b Design Test&Scope 1 X 10c Dtain resources 1 X 10b Perform Evaluation 5 X 10f Instrument Forge 3 X 10f Update Website 0.5 4 10h Update Website 0.5 4 11 4SS Deliverables X 11 4SS Deliverables X 11 4SS Deliverables X 11 4SS Deliverables X 11 4SS Deliver		Assemble Sub Intake	0.5	0.5					-	-				X		-			-		100	1		-		
Bit Assemble Burner 0.5 0.5 9 Take Dev Pictures 1 1 9 Update Website 0.2 2 subtotal: 2.4 4.2 10 Device Evaluation 0 10a List Parameters 1 1 11 0 X 12 0 X 13 0 X 14 0 X 15 0 X 16 0 X 17 0 X 18 Get Report Guide 1 19 18 X X 10 Update Website 0.5 X 10 18 2 X X 10 18 28 X X 11 455 28 X X 11 10 X X X 10 18 18 X X X 10 18 2 2 X X 10 18 10 <td>90</td> <td>Accombic Cab Indate</td> <td>0.0</td> <td>0.0</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td>-</td> <td>-</td> <td></td> <td>-</td>	90	Accombic Cab Indate	0.0	0.0						-									-				-	-		-
Se Take Dev Pictures 1 1 1 9e Take Dev Pictures 0.2 2 X 10 subtotal: 2.4 4.2 10 Device Evaluation X X 10a List Parameters 1 1 X 10b Design Test&Scope 1 5 X 10c Dtain resources 1 1 X 10d Make test sheets 2 1 X 10f Instrument Forge 3 3 X 10f Instrument Forge 3 3 X 10f Ake test sheets 2 1 X 10f Instrument Forge 3 3 X X 10f Instrument Forge 3 3 X X 10f Update Website 0.5 4 X X X 10h Update Website 0.5 4 X X X X 11 45D Eliverables X X X X X X 11 45D Eliverables X X X X X X	90	Assemble Burner	0.5	0.5		 				-	-			X		-			-	-	-	÷				
9 Update Website 0.2 2 10 Device Evaluation 1 10a List Parameters 1 1 10b Design Test8.Scope 1 5 10c Obtain resources 1 1 10d Hist Parameters 1 1 10d Hist Personres 1 1 10d Hist Petstameters 2 1 10d Hist Petstameters 3 3 10f Instrument Forge 3 3 10g Test Plan* 1 1 10h Petform Evaluation 5 1 10h Update Website 0.5 4 10h Update Website 1.5 28 11 435 Deliverables X 11 10h Make Rep Dutline 3 12 1 X X 11 10 X X X X 11 10 X X X <td>90</td> <td>Take Day Pictures</td> <td>1</td> <td>- 1</td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td>-</td> <td>-</td> <td></td> <td>-</td> <td>Ŷ</td> <td></td> <td>-</td> <td></td> <td></td> <td>-</td> <td></td> <td>-</td> <td>-</td> <td></td> <td>-</td> <td></td> <td></td>	90	Take Day Pictures	1	- 1					-	-	-		-	Ŷ		-			-		-	-		-		
Subtoal: 24 4.2 10 Device Evaluation	96	Update Website	0.2	2						-				0		-			-		-	+	-			-
Image: Substain of the second secon	U	opuale website subtotal:	2.4	42		-			-	-	-		-	0					-	-		-	-	-		
10 Device Evaluation Image: Constraint of the set		Subtotal.	2.4	4.2																		+		-		
10a List Parameters 1 1 X 10b Design Test&Scope 1 1 X 10b Obtign resources 1 1 X X 10b Obtign resources 1 1 X X X 10b Obtign resources 3 X X X X 10b Plan analyses 3 X X X X 10f Instrument Forge 3 X X X X 10f Instrument Forge 3 X X X X 10g Test Plan* 1 2 X X X X 10h Perform Evaluation 5 5 X X X X X 10h Update Website 0.5 4 X	10	Device Evaluation																	<	>						
10b Design Test&Scope 1 5 X 10c Dbtain resources 1 1 X 10d Make test sheets 2 1 X 10e Plan analyses 3 5 X X 10f Instrument Forge 3 3 X X 10f Perform Evaluation 5 5 X X 10h Perform Evaluation 5 5 X X 10h Update Website 0.5 4 X X 11 495 Deliverables X X X 11c Write Report 5 5 X X 11b Make Rep Outline 3 3 X X 11c Write Report 5 5 X X 11f Make CD Deliv, List 2 X X X	10a	List Parameters	1	1											2	X										
10c Obtain resources 1 1 10d Make test sheets 2 1 10e Plan analyses 3 5 10f Instrument Forge 3 3 10g Test Plan* 1 2 10h Perform Evaluation 5 5 10i Take Testing Pics 1 1 10h Update Website 0.5 4 10h Update Website 0.5 4 11 495 Deliverables X X 11 Get Report Guide 1 1 11b Make Rep Dutline 3 3 11c Write Report 5 5 11d Make Slide Dutline 3 3 11e Create Presentation 3 3 11e Create Presentation 3 X X 11f Make CD Deliv. List 2 X X 11g Project CD* 2 X X 11g Project CD* 2 X X	10b	Design Test&Scope	1	5											2	X								-		
10d Make test sheets 2 1 X X 10e Plan analyses 3 5 X X 10f Instrument Forge 3 3 X X 10g Test Plan* 1 2 X X 10h Perform Evaluation 5 5 X X 10h Perform Evaluation 5 5 X X 10h Update Website 0.5 4 X X 10h Update Website 0.5 4 X X 11 495 Deliverables X X X 11a Get Report Guide 1 1 X X 11b Make Rep Outline 3 3 X X 11c Write Report 5 5 X X 11d Make Slide Outline 3 3 X X 11e Write 495 CD parts 2 2 X X 11f Make CD Deliv. List 2 2 X X 11f Write 495 CD parts 2 2 X X 11g Project CD* 2 2<	10c	Obtain resources	1	1											2	X						T		-		_
10e Plan analyses 3 5 X 10f Instrument Forge 3 3 X 10g Test Plan* 1 2 X 10h Perform Evaluation 5 X X 10h Update Vebsite 0.5 4 X X 10h Update Website 0.5 4 X X 10h Update Website 0.5 4 X X 10h Update Website 0.5 4 X X 10h Explored bles X X X X 11 495 Deliverables X X X X 11a Get Report Guide 1 1 X X 11b Make Rep Dutline 3 3 X X X 11d Make Side Dutline 3 3 X X X 11d Make Side Dutline 3 3 X X X 11f Make Side Dutline 3 3 X X	10d	Make test sheets	2	1						1				-	ŝ	ż						1	-	-		
10f Instrument Forge 3 3 X X 10g Test Plan* 1 2 X X X 10h Perform Evaluation 5 5 X X X X 10h Perform Evaluation 5 5 X X X X 10h Update Website 0.5 4 X X X X 10h Update Website 0.5 4 X X X X 10h Update Website 0.5 4 X X X X X 10h Update Website 0.5 4 X <	10e	Plan analuses	3	5											ż	ż								-		-
Total Est Huan* Sign	106	Instrument Forge	3	ž						-				-	- 3	ż			-			-		-		
Toth Perform Evaluation 1 2 X <thx< th=""> X<td>100</td><td>Test Plan*</td><td>1</td><td>2</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>i i</td><td>ż</td><td></td><td></td><td></td><td></td><td></td><td>-</td><td>-</td><td>-</td><td></td><td>-</td></thx<>	100	Test Plan*	1	2											i i	ż						-	-	-		-
101 Take Testing Pics 1 101 Take Testing Pics 1 10h Update Website 0.5 subtotal: 18.5 11 495 Deliverables 11 11 116 Get Report Guide 1 117 11 118 Get Report Guide 1 119 11 110 Make Rep Dutline 3 110 Make Side Dutline 3 116 Create Presentation 3 116 Write Report 5 116 Write Report 5 117 Make CD Delive. List 2 118 Write 495 CD parts 2 119 Project CD* 2 119 Subtotal: 21.5 110 Total Est. Hours= 150.4 110 Total Est. Hours= 174.7	106	Perform Evaluation	5	5		 			-	-			-	-			X	X	XY	2	-	-		-		
10h Up date Up date 0.5 4 10h Up date Website 0.5 4 11 495 Deliverables 1 1 11a Get Report Guide 1 1 11b Make Rep Dutline 3 3 11c Write Report 5 5 11d Make Slide Dutline 3 3 11f Make Slide Dutline 3 3 11d Make Slide Dutline 3 3 11f Make CD Deliv. List 2 2 11f Write 495 CD parts 2 X 11f Update Website 0.5 0.5 11g Project CD* 2 2 X 11g Project CD* 2 2 X 11g Project CD* 2 2 X 11g Project CD* 150.4 174.7 =Total Actual Hrs 4 Labort\$ 100 15040 15040 15040 16040	101	Take Testing Pice	1	1		-			-	-	-		-	-		-	0	0	0 1	1	-	+	-	-		
Infl Opdate website 0.3 4 subtotal: 18.5 28 11 495 Deliverables	106	Lodate Wabaita	0.5	4		 			-	-	-		-	-	_	-	~	^	0		-	+		+		
11 495 Deliverables 11a Get Report Guide 11b Make Rep Dutline 33 X 11b Make Side Outline 33 X 11d Make Side Outline 33 X 11d Make Side Outline 33 X 11d Make CD Deliver. List 11f Make CD Deliver. List 11f Update Vetasite 0.5 0.5 11g Project CD* 11g Project CD* 11g Project CD* 11g Project CD* 11g Total Est. Hours= 150.4 174.7 =Total Actual Hrs Labor\$ 100 100 15040	IUN	opuale website	10 E	20		 				-	-		-	-		-		-	0	-	-	÷		-		
11 495 Deliverables 11a Get Report Guide 1 11b Make Rep Outline 3 11c Write Report 5 11d Make Silde Outline 3 11d Make CD Deliver, List 2 11f Make CD Deliver, List 2 11f Update Website 0.5 11g Project CD* 2 11g Total Est. Hours= 150.4 116 Haurs= 174.7 =Total Actual Hrs 4		Subiolai.	10.0	20					-	-	-		-	1		-			-		-	+		-		
11a Get Report Guide 1 1 11b Make Rep Outline 3 3 11c Write Report 5 5 11d Make Slide Outline 3 3 11e Create Presentation 3 3 11f Make CD Deliv. List 2 2 11e Write 495 CD parts 2 2 11f Update Website 0.5 0.5 11g Project CD* 2 2 11g Project CD* 2 2 Total Est. Hours= 150.4 174.7 =Total Actual Hrs 5 5	11	495 Deliverables																								
11b Make Rep Outline 3 3 11c Write Report 5 5 11d Make Slide Outline 3 3 11d Make Slide Dutline 3 3 11e Create Presentation 3 3 11f Make CD Deliv. List 2 2 11e Write 495 CD parts 2 2 11f Update Website 0.5 × 11g Project CD* 2 × Total Est. Hours= 150.4 174.7 Total Est. Hours= 150.4 174.7	11a	Get Report Guide	1	1															2	<						
11c Write Report 5 5 X X X 11d Make Silde Outline 3 3 X X 11e Create Presentation 3 3 X X X 11f Make CD Deliv. List 2 X X X X 11e Write 495 CD parts 2 X X X X 11g Project CD* 2 X X X 11g Deliv. List 2.15 X X X 11g Deliv. List 2.15 X X X 11g Delive. 100 15040 174.7 = Total Actual Hrs X X	11b	Make Rep Outline	3	3															2	$\langle \rangle$	<					
11d Make Slide Outline 3 3 11e Create Presentation 3 3 11f Make CD Deliv. List 2 X 11f Make CD Deliv. List 2 X 11e Write 495 CD parts 2 X 11f Update Website 0.5 X 11g Project CD* 2 X 11g Project CD* 2 X Total Est. Hours= 150.4 174.7 Labor\$ 100 15040	11c	Write Report	5	5																>	XX	X	1			
The Create Presentation 3 3 X X The Make CD Deliv. List 2 2 X X The Write 495 CD parts 2 2 X X The Update Website 0.5 X X X The Update Website 0.5 X X X Total Est. Hours= 150.4 174.7 =Total Actual Hrs X X Labor\$ 100 15040 X	11d	Make Slide Outline	3	3																		X		1		
11f Make CD Deliv. List 2 2 The Write 495 CD parts 2 2 11f Update Website 0.5 X 11g Project CD* 2 X subtotal: 215 X X Total Est. Hours= 150.4 174.7 =Total Actual Hrs Labor\$ 100 15040 Image: Construct of the second seco	11e	Create Presentation	3	3																		X	X			
The Write 495 CD parts 2 2 X The Update Website 0.5 0.5 X Tig Project CD* 2 2 X Subtotal: 21.5 21.5 X Total Est. Hours= 150.4 174.7 =Total Actual Hrs Labor\$ 100 15040 X	11F	Make CD Deliv, List	2	2																			X	X		-
11f Update Website 0.5 X 11g Project CD* 2 2 X subtotal: 21.5 21.5 X X Total Est. Hours= 150.4 174.7 =Total Actual Hrs X X Labor\$ 100 15040 X X X X	11e	Write 495 CD parts	2	2																			X	X		
Tig Project CD* 2 2 subtotal: 21.5 X Total Est. Hours= 150.4 174.7 =Total Actual Hrs Labor\$ 100 15040 Image: Comparison of the second s	11F	Update Website	0.5	0.5																				X		
subtotal: 21.5 21.5 0 0 Total Est. Hours= 150.4 174.7 = Total Actual Hrs 100 15040	110	Project CD*	2	2					-	1			-						-	-	-	-	-	X		
Total Est. Hours= 150.4 174.7 = Total Actual Hrs Labor\$ 100 15040		subtotal	215	215															+			-		1	1	0
Total Est. Hours= 150.4 174.7 = Total Actual Hrs Labor\$ 100 15040		Subtotal.	21.0	21.0						-						-				-	-	-	-	-		
Labor\$ 100 15040		Total Est. Hours=	150.4	174.7		-	Total Ac	tual Hrs		-				1		-			-		-	-	-	1	+++	
	Labor\$	100	15040																					1		

Appendix G

G1

Procedure

- 1. Install burner being tested to the forge.
- 2. Weigh the propane tank being used.
- 3. Light the forge at 30psi of propane input and close the opening.
- 4. Start the timer and watch the temperature and propane regulator.
- 5. Adjust the regulator to maintain 30psi.
- 6. Stop the timer when the forge reaches 1000 °F and disconnect the propane tank.
- 7. Brush the frost off the propane tank and weigh it again.
- 8. Reinstall the propane tank and set the regulator to 15 psi and place one of the steel samples in the forge, directly below the flame. Let it soak in the heat for 10 minutes.
- 9. Allow the steel sample to air cool outside of the forge before the visual oxidation inspection.

Testing procedure will be performed for both the engineered burner and the benchmark burner and the results will be compared to assess the performance of the engineered burner.

G2

Burner	Time to Heat (min:sec)	Initial Tank Weight (lb)	Final Tank Weight (lb)	Propane Consumed (lb)	Rate of Consumption (lb/min)
Benchmark					
Engineered					
Improvement		Х	x	Х	

G3 Raw Data

Burner	Time to Heat (min:sec)	Initial Tank Weight (lb)	Final Tank Weight (lb)	Propane Consumed (lb)	Rate of Consumption (lb/min)
Benchmark	18.39	28.9	24.0		0.263
Engineered	15:38	22.9	21.0		0.122

Burner	Time to Heat (min:sec)	Initial Tank Weight (lb)	Final Tank Weight (lb)	Propane Consumed (lb)	Rate of Consumption (lb/min)
Benchmark	18.39	28.9	24.0	4.9	0.263
Engineered	15:38	22.9	21.0	1.9	0.122
Improvement	16.2%				53.6%

Engineered Burner:

Benchmark Burner:



Appendix H

Caleb DesJardins

805 E 5th Ave #5B Ellensburg, WA (425) 286-5028 Caleb.Desjardins@cwu.edu

Experience

December 2014 - August 2017 Village Eatery and Tea Company

Serving/Hosting

August 2017 - September 2018 Starbucks

High volume customer service

Education

2013 - 2018

Cascadia College

- Running Start
- Mechanical Engineering focus
- Associate degree of Science Transfer Track
- Associate degree of Integrated Studies

Accomplishments

- · Running Start student in high school
- Built computers
- Made tutorials on fixing a laptop for iFixit.com
- Designed and built multiple blacksmithing forges, propane burners, and other blacksmithing equipment

Summer 2019

NorthStar Casteel

- Internship
- · Quality control on casting project
- Lead project to organize shipment of casting patterns

2018-Present

Central Washington University

- Bachelor's in Mechanical Engineering Technology, June 2020
- Dean's list student
- ASME club member
- Designed and built a propane burner for senior project
- · Certified SolidWorks associate

Hobbies

- · Blacksmithing/Metal art
- Fixing/building cars
- · Strength training

Skills

- · Autodidactic in many disciplines.
- Motivated and hardworking individual. Frequently sought out by employers and coworkers for shift coverage because of reputation for good work ethic.
- Can complete tasks in a timely manner. Able to solve problems logically under pressure.
- Experienced and skilled in solving practical/mechanical problems.

Summary

Talented in understanding mechanical things and solving mechanical problems from a young age. Ability to self-teach in any skill to pursue interests and hobbies. History of being a reliable employee with exceptional work ethic.

Appendix J

Engineering Technologies, Safety, and Construction Department

JOB HAZARD ANALYSIS {Insert description of work task here}

Prepared by: Caleb Desulardins.	Reviewed by:	
	Approved by:	

Location of Task:	CWU Machine lab
Required Equipment / Training for Task:	Manual lathe, manual milling machine, band saw, and PPE/ ETSC safety training
Reference Materials as appropriate:	https://ehs.berkeley.edu/job-safety-analysis-jsas-listed-topic https://ehs.unc.edu/workplace-safety/jsa/

(Check	Per: the box for requir	sonal Protec ed PPE and list	tive Equipmer any additional/spe	t (PPE) Reque	i red ised in "Controls"	section)
	0	Θ	M	2		益
Gloves	Dust Mask	Eye Protection	Welding Mask	Appropriate Footwear	Hearing Protection	Protective Clothing

(if DESCRIPTION	HAZARDS	CONTROLS
Turning features on the Injector, Intake, Burner Body, and nozzle.	Entanglement in unguarded moving parts Injury due to improper machine operations Tools and objects can fall and be propelled at the operator. Hand/finger contusion due to tool slippage from securing chuck or collet Bodily injury and/or damage to workpiece from incorrect feed rate Dull tools and improper height lead to bad surface finishes, out of tolerance parts and potentially a hazardous situation. Hand/finger contusion due to tool slippage from tightening chuck jaws or collet Injury to exposed body parts at points of operation	 Inspect guards prior to work. Locate and ensure you are familiar with all machine operations and controls. Remove unsecured tools and objects from the lathe. Use correct tool to secure chuck or collet Refer to operations manual and set proper lathe speed Use correct and properly sharpened tool Use correct tool to secure chuck jaws and collet to workpiece Keep body parts and clothes away from the point of correction

 Eye injury from debris 	•	Wear PPE during operation
 Injury to hands from milling blades Hearing damage from machine noise 	•	Never disconnect safety shields from milling blades Wear hearing protection, such as ear plugs, if operating machine for periods extending more than 10 minutes.
 Possible eye injury from wire stitches thrown out by milling blade Crushing finger hazard from book clamp 	-	Wear safety glasses during operation. Do not hold book at spine when activating book clamp. Hold book at the face.
Cut/Puncture/Scrape Hazard Pinch Hazards	•	Keep hands away from pinch points and blade
	Eye injury from debris Injury to hands from milling blades Hearing damage from machine noise Possible eye injury from wire stitches thrown out by milling blade Crushing finger hazard from book clamp Cut/Puncture/Scrape Hazard Pinch Hazards	Eye injury from debris Injury to hands from milling blades Hearing damage from machine noise Possible eye injury from wire stitches thrown out by milling blade Crushing finger hazard from book clamp Cut/Puncture/Scrape Hazard Pinch Hazards

1